Work	Orde	r ID	69294
Part day . A	1-06	0011 1	.00.12 DA



Page 1

Friday, May 06, 2011 1:00:13 PM Item ID: D3272-1 Revision ID: Item Name: Step **Start Qty: 10.00** Start Date: 5/6/2011 Required Date: 5/27/2011 Req'd Qty: 10.00 Reference: Process Plan: MF Approvals:

Accept



Setup Start



Stop

Cust Item ID:

Customer:

Date: 11-05-09

Tooling:

SPC (Y/N):

Date:

Date:

Run Start

Qty

Stop

Reject Reject Insp.

Sequence ID/ Work Center ID Operation Description Set Up/ **Run Hours** Tool ID

Tool # Plan Code

Accept Qty

Number

Stamp

Draw Nbr D3272

Large Fab

Large Fab

Rev B

Revision Nbr

100

Large Fab

Date:

Memo

0.00

0.00

SQUARE ONE END BEFORE CUTTING OTHER END

1-Cut D2622-120 extrusion to 116.25" long as per Dwg D3272 using cutting table setup DT 8185-2A

2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets.

3-Deburr

110

QC

Quality Control

QC6- Inspect dimensions to drawing

Memo

0.00

> 11/15/12

0.00

Dart Aerospace Ltd

					·					
W/O:			WC	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•				7				
							*			
Part No	*	PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:					
	R	esolution:	Dispositio	n;	QA: N/C	Clos	ed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)				
		Description of NC		Corrective Action Sect	tion B		Verifi	cation	Approval	Approval
DATE STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section C			Chief Eng	QC Inspector	
•										

NOTE: Date & initial all entries

Page 2

Item ID:

D3272-1

Accept



Setup Start

Stop



Revision ID:

Item Name:

Step

Required Date: 5/27/2011

5/6/2011

Start Qty: 10.00 Req'd Qty: 10.00

Cust Item ID:

Customer:

Reference:

Start Date:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Sequence ID/ Work Center ID

120

Packaging

Packaging

Operation Description

Memo

Identify as per dwg & Stock Location: WA

0.00

0.00

Tool ID

Tool # Plan Code Accept Qty

Reject Qty

Reject Number

Insp. Stamp

130

QC

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

11/5/1640 11-05-16

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										-
Part No		PAR #:	Fault Cate	gory:	NCR	: Yes N	lo DQ	A:	Date:	
		esolution:								
NCR:		WORK ORDI	ER NON-CONFORM	IANCE	(NCR)		¢			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Se Action Description Chief Eng	ection B	Sign & Date		cation ion C	Approval Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries

Picklist Print

Friday, May 06, 2011 1:00:10 PM

Work Order ID: 69294

D3272-1 Parent Item:

Parent Item Name: Step



Start Date: 5/6/2011

Required Date: 5/27/2011

Page 1

Start Qty: 10.00

Required Qty: 10.00

Comments:

IPP Rev:A

New Issue 07-06-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C		Manufactured	No			100	Each	100.0000	1	10			
Step Extrusion										A.E	_x10		-05 -

Step Extrusion

Location	Loc Qty	Loc Code	
HALL	9		
64409	9		
WA	91		
46910	2		***************************************
66970	89		


Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	SES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes				
	Resolution: Disposition:					losed:		Date: _	
NCR:			VORK OR	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC			tion B	Verifi	cation	Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		tion C	Chief Eng	QC Inspector
								:	
									Parameter and the second secon

NOTE: Date & initial all entries



9 B		DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAL		
	CHECH	(ED _	APPROVED	DRAWING NO.	REV. B
	(E	世	D3272	SHEET 1 OF 3
į	DATE			TITLE	SCALE
	07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
	Α		04.03.01	NEW ISSUE	
	В		07.05.18	D3272-1 WAS D2622-120	



QTY -041	QTY -042	PART NUMBER	DESCRIPTION
Х		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:


- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


	•
·	



•		



DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAN	
CHECKED	APPROVED ,	DRAWING NO.	REV. B
LE	- AT	D3272	SHEET 3 OF 3
DATE		TITLE	SCALE
07.05.18	•	STEP ASSEMBLY, HI LONG	1:20



\$. . . • • • •